Scanning Spray for Optical 3D Measurement

Jet Swan

<section-header><section-header><section-header><section-header><section-header><section-header>

Anti-Glare: from Shiny to Black

By forming a white surface on a glossy or black surface, which is difficult for optical non-contact measurement, and obtaining a suitable amount of reflected light for measurement, it is possible to easily measure 3D shapes.





Thin Coating: stable and reliable

JetSwan uses a specially selected spray material. The effect of the unevenness of the applied powder is minimal, and the shape of the measurement object can be accurately measured.



Quick Dry: Fast and Easy

Quick-drying properties prevent uneven coating due to dripping.



Comparison of layer thickness

- JetSwan forms an ultra-thin layer on the object surface, which has the least influence on the measurement.
- Test result of layer thickness :
 <existing product> 5 ~ 10 μm
 <JetSwan> ~ 0.5 μm
- Layer thickness measurement :
- Spray twice from 200mm on optical flat covered by masking tape and move the spray at a speed 150mm/s. Tear off the tape, then measure the edge between coating and uncoating section by microscope. The value of edge will be layer thickness.



Layer thickness: 5 ~ 10 µm

Layer thickness: ~ 0.5 μm

How to use: Easy Steps

- 1. Shake the spray for 30 seconds with a clang sound from inside.
- 2. Spray Jet Swan from 200 mm away from the object.
- Spray on the surface of project and move the can at a consistent pace at a speed 150 mm/sec to achieve an even coating.
- 4. If coating is not enough, wait for the prior spray to dry and then spray again.
- 5. It is better to spray twice for glossy surface of metal machining, five times for surface of black resin.
- 6. When removing the applied powder, wash with water if it can be washed with water. Remove possible cleaning materials using a brush or the like.





Product Information

Ingredients: isopropanol, calcium carbonate, butane Content @ Can: 420 ml / 14.2 oz Manufacture: FUJIOKA CO., Ltd. Contact: jetswan@fujioka-coltd.co.jp

Usage notes

- Use in a well-ventilated place.
- Wear protective gloves / glasses / mask / clothes.
- Do not inhale gas / mist / steam / spray.
- Do not spray onto a naked flame or any incandescent material.
- Wash hands after using.
- Please check our Safety Data Sheet for further information and before usage.

Warning

- Do not use near an open flame.
- Avoid prolonged exposure to sunlight or heat sources over 40 / 104 that may cause bursting.
- Do not dispose it in fire.
- Please use it up before disposal.
- Do not eat or smoke when using.